
## LEVERAGING SURVEY TECHNOLOGY TO RESTORE COMMUNITIES IN THE WAKE OF HURRICANE IAN RESILIENCE





## GRANT FICHTER, PSM

- Survey and Mapping Manager
- Surveying runs in the Family
- 24-year career all with AIM



## ABOUT AIM

#### Group 2

• Project Development and Environment (PD&E) Studies

#### Group 3

• Highway Design – Roadway

### Group 7

• Traffic Operations Design

### Group 8

• Surveying and Mapping

### Group 10


• Construction Engineering Inspection

### Group 13

• Planning

### Facts and Stats

- Family owned and operated for 43 years with ties to FDOT for all 43 of those years.
- Currently 165+ professionals and administrative staff
- Successfully completed over 10,000 projects
- Served over 75 public clients and 1,200 private sector clients



### SURVEY & MAPPING CAPABILITIES

RESILIENCE



- As-Built Survey
- Boundary Survey
- Construction Layout
  Survey
- Control Survey
- Hydrographic Survey
- Mean High Water Line Survey
- Quantity Survey
- Specific or Special Purpose Survey
- Pre and Post Construction Survey
- Topographic Survey

- Terrestrial Mobile and Static LiDAR
- Parcel / Easement Sketch and Descriptions
- Subsurface Utility Designation & Excavation
- Designating and Locating
- Maintained Right-of-Way Survey
- Expert Technical Witness
- Global Positioning System (GPS) Survey

## SURVEY AND MAPPING

Hydrographic Survey

RESILIENCE

W Hydrographic Sunsy

## HYDROGRAPHIC SURVEY

- Multibeam Hydrographic Survey
- Bathymetric Mapping
- Magnetometry
- Side Scan
- Pre & Post Dredge Survey
- Dredging Volume Calculations
- Turbidity Testing


- Port/Harbor Maintenance Survey
- Beach Nourishment Survey
- River & Estuary Survey
- Beach & Canal Survey
- Navigation Condition Survey
- Emergency Post Storm Survey



### HYDROGRAPHIC MULTI BEAM

Big Carlos Pass,

Fort Myers Beach



# HURRICANE IAN

September 2022

### DEVASTATING LANDFALL

30°N -

25°N

The hurricane came ashore near Cayo Costa, in Lee County, as a major Category 4 storm, but its maximum sustained winds were only 7 mph less than a Category 5.


### POST STORM



### POST STORM



## SURVEY RESPONSE TIMELINE



## TASK OBJECTIVES

- Targets & control points
- Shoot components of bridge, still stable?
- Use See Bottom to assess channels for boat and barge access
- Use See Bottom to determine cracks, breaks or severed pilings in water, not visible to divers

### CHALLENGES FACED

- Communication
  - Cell lines were down
  - Was able to communicate by email
  - Collecting data by use of radio signal rather than cell
- Mobilization risky
  - Debris on roads
  - Lack of gas
  - Boat ramps destroyed
  - Channel markers missing

### WHAT WE LEARNED FOR FUTURE

- Purchase equipment with radio communication
- Fuel up vehicles and boats
- Don't leave critical equipment on the floor

### THANK YOU

Grant Fichter, PSM

AIM Engineering & Surveying, Inc.

gfichter@aimengr.com



